Technical Bulletin

Subject: ADDITION OF FOURTH REPAIR KIT PIECE NUMBERS

The Bendix Tu-Flo 501 compressor is currently being remanufactured to fourth repair sizes. Below is a listing of all Tu-Flo 501 compressor kits and their respective repair sizes if applicable. The new piece numbers are shown in a **boldface** type, all others are for reference only.

Please update your Service Parts Catalog to reflect these changes.

Kit No.	Description	Repair Size
106105	Piston Ring Set	Standard
106106		.010 O.S.
106107		.020 O.S.
106108		.030 O.S.
5005216		**.040 O.S.**
106109	Piston & Wrist Pin Kits	Standard
106110		.010 O.S.
106111		.020 O.S.
106112		.030 O.S.
5005217		**.040 O.S.**
286254	Connecting Rod Insert Kit	Standard
286255	Non Thru Drive	.010 O.S.
286256		.020 O.S.
286257		.030 O.S.
5005218		**.040 O.S.**
287058	Connecting Rod Insert Kit	Standard
287059	Thru Drive	.010 O.S.
287060		.020 O.S.
287061		.030 O.S.
5005219		**.040 O.S.**
287043	Field Maintenance Kit	
279615	Unloader Kit	
101558	Gasket Kit	